
## WIRING INSTRUCTIONS



NOTE: ALL LEADS MUST BE HELD TO ± 1/8" ALL FIELD LEADS TO BE MEASURED FROM AND PERPENDICULAR TO LAMINATIONS. ALL LEAD LENGTHS ARE BEFORE STRIPPING.

Electrical Parts

Where Terminal and Connector Combinations are Specified, See Electrical Parts	s Chart
For Part No. and Quantity. See Drawing For Actual Hook-up.	

																						CRMINAL DESCRIP	IION		
	WIRING SPECIFICATIONS														Code	Part No.	Qnty.								
Wire	Wire	Ga	Lgth		Terminal			Con	nnector		Wire	Wire	1	Lgth		minal		Connector		וד'	23-74-0330	4			
Color	No.		in.	<u>T1</u>	T2	T3	T4	C1 C	2 C3	C4	Color	No.	.00.	in.	<u>T1</u>	T2	T3	T4	C1 C	2 C3C4	T2	23-74-0050	1		
Blue	1	Fid.	1-3/8								Green	6	Cord	3		×					CONNECTOR DESCRIPTION				
White	2	Fid.	3-1/4	x																	Code	Part No.	Qnty.		
								i																	
Blue	3	20	2-1/4	X		1				i l							i				SWITCH DESCRIPTION				
Black	4	Cord	3	х																	Code	Part No.	Qnty.		
White	5	Cord	3	x																	S1	23-66-0280	1		
1		1				1	1			1			L				1	1					1		

Form OE-24